



Rail

Production facility inspection on the basis of the agreement in the testing and certification rules performed on **2021-06-09**

Licence holder:

PILZ GmbH & Co. KG

Felix-Wankel-Straße 2
73760 Ostfildern
Deutschland

Production facility:

Kunbus GmbH

Heerweg 15c
73770 Denkendorf
Deutschland


This facility manufactures products certified by TUV SÜD PRODUCT SERVICE for the following Product Category/ies:

P2HZ, PNOZclassic, PNOZ X, PNOZcompact, PNOZelog, PNOZpower, PNOZsigma, PZE, Safety Monitoring Relay, PNOZmulti, PNOZmulti2

The production facility inspection was conducted according to the instructions of TUV SÜD PRODUCT SERVICE. The requirements to a faultless and homogeneous fabrication as stated in the test and certification rules are met. The applied and documented quality assurance procedures were found suitable.

The next inspection will be conducted latest in **12 months** starting with the date of inspection.

Denkendorf, 2021-06-09


Wolfgang Mayer – TA-RA/MUC